

# Just-In-Time Report

## Defective SCOTT SKA-PAK Cylinders

February 1, 2007

2007-RL-HNF-0006

Tracking No: 394

**Site/Facility:** Hanford/All

**Event:** CH2M Hill announced that some Scott fiberglass wrapped 5 minute cylinders tested at OxArc had failed the hydrostatic test. The two cylinders that failed their hydrostatic test were made by Luxfer who has not at this time issued a safety notice or recall of the product. We are working together with CH2M and Scott/Tyco to identify the extent of this issue.

**Important Points:**

- **All Scott fiberglass wrapped 5-minute cylinders must be immediately taken out of service, and tagged as 'out of service', unless they have at least two hydrostatic tests (the original and 3 year re-test).**
- **Tagged out bottles should be sent to the Hanford Fire Department (Scott SCBA shop 609G) who will coordinate the testing. These cylinders are used exclusively on the Scott Brand SKA-PAK plus units.**
- **Once a bottle has been tested and passed, it can be returned to service. The testing is being performed by OxArc in Pasco.**
- **This testing requirement applies to cylinders manufactured by both Luxfer and SCI.**

**Contributors:** Manufacturing/unknown