



From: Ty Blackford, President and CEO Log Number: CH1712-20
Date: December 20, 2017
To: The CH2M HILL Plateau Remediation Company Team
(Please forward to those who may not have seen this message)
Subject: PFP UPDATE - VEHICLE SURVEYS

This last week has been a difficult time for CHPRC, specifically at PFP. Mistakes were made at several levels that created a situation that is unacceptable for worker safety, protection of the environment, and service to our customer. However, we must learn from these mistakes in our journey as a learning organization and we are, and will, be taking actions in response to these mistakes. Radiological surveys to ensure we have our arms around the situation have been completed and no further contamination has been detected. The PFP project is maintaining expanded control boundaries, including surrounding areas on the Hanford Site and access to the PFP area is still restricted.

We completed radiological surveys of personnel who work at the PFP location, along with their vehicles as well as any other vehicles we have been made aware of; government or personal. However, we understand additional site employees may have driven in the area and might be concerned about potential contamination spread. If they drove near PFP since Dec. 15, or used the dirt road immediately south of the PFP fence line, from Dec. 8 to Dec. 14 they should have their vehicles surveyed. Please contact Sheila Godfrey with your vehicle location, color and license plate number so we can dispatch a survey team.

Our focus continues to be on the safety of our workers and we want everyone to have no doubt they are safe and protected. Thank you in advance for your cooperation and patience during this process.