


# Tank Farm Area Cleanup Decision-Making

## Single Shell Tank System Closure (tanks, structures and pipelines)

- Washington State Hazardous Waste Management Act (Resource Conservation & Recovery Act Closure Plan for dangerous waste constituents)

+

- Department of Energy (DOE) Order 435.1 (435.1 closure plan for radioactive residual constituents in tanks and components of tanks)



# DOE Order 435.1 and 3116

---

- Summary of DOE O 435.1 differences with 3116
- Either 435.1 Waste Incidental to Reprocessing (WIR) or 3116 Waste Determination required for High-Level Waste (HLW) origin residual being left behind
- 3116 only replaces WIR – all other 435.1 requirements still apply
- 435.1 WIR not “tested” yet
- 3116 preserves role for State
  - State issued permit or closure plan
- 3116 ensures Nuclear Regulatory Commission involvement through consultation and monitoring
  - Monitoring executed in coordination with State

# Now Is the Time to Discuss Closure Waste Management Area C

