

CONTENTS

PROLOGUE.....	ix
EXECUTIVE SUMMARY	xi
1.0 INTRODUCTION	1-1
1.1 SCOPE OF THE REPORT	1-5
1.2 INVESTIGATION SCOPE, PURPOSE, AND METHODOLOGY	1-5
1.2.1 Scope	1-5
1.2.2 Purpose	1-5
1.2.3 Methodology	1-6
2.0 FACILITY AND PROGRAM DESCRIPTION SYNOPSIS	2-1
2.1 SITE FACILITIES	2-1
2.2 WORK CONTROL	2-4
2.3 RADIOLOGICAL CONTROL.....	2-4
2.4 BIOLOGICAL VECTOR CONTROL PROGRAM	2-4
2.5 SOLID WASTE DISPOSAL PRACTICES	2-5
3.0 THE INCIDENT CHRONOLOGY	3-1
3.1 CHAIN OF REASONING.....	3-1
3.2 TIMELINES.....	3-3
3.3 DETAILED DATA	3-3
4.0 SYNOPSIS OF CAUSAL ANALYSIS	4-1
4.1 DISCUSSION	4-1
4.2 ROOT CAUSE.....	4-2
4.3 DIRECT CAUSE	4-2
4.4 CONTRIBUTING CAUSES	4-3
5.0 ASSESSMENT OF EVENT	5-1
5.1 WORKER AND PUBLIC SAFETY	5-2
5.1.1 Safety of Workers and Public at the City of Richland Landfill.....	5-3
5.2 RADIOLOGICAL CONTROL PRACTICES	5-3
5.2.1 Recovery Actions	5-3
5.2.2 Sample Management	5-5
5.3 BIOLOGICAL VECTOR CONTROL	5-5
5.3.1 Environmental Surveillance and Monitoring of Biological Species.....	5-6
5.3.2 Flying-Insect Trap Monitoring	5-7
5.3.3 Chemical Insecticide Control.....	5-7
5.4 SOLID WASTE DISPOSAL PRACTICES	5-8
5.4.1 Landfill Practices	5-8
5.4.2 New Refuse Disposal Process.....	5-9
5.5 MANAGEMENT SYSTEMS	5-11
5.5.1 Incident Response Processes	5-11
5.5.2 Employee Communications.....	5-16
5.5.3 Media Relations	5-17

5.5.4 City and Regulatory Interface.....	5-18
5.6 OPPORTUNITIES FOR ENHANCED OPERATIONS.....	5-20
6.0 CONCLUSIONS	6-1
6.1 LESSONS LEARNED	6-1
6.2 RECOMMENDATIONS.....	6-2
7.0 REFERENCES	7-1

APPENDICES

APPENDIX A	BIOASSAY AND INTERNAL DOSIMETRY	A-1
APPENDIX B	CONTAMINATION RISK AND LABORATORY ANALYSIS	B-1
APPENDIX C	INVESTIGATIVE TEAM CHARTERS AND MEMBERS	C-1
APPENDIX D	CAUSAL ANALYSIS.....	D-1
APPENDIX E	FLYING-INSECT MONITORING TRAP LOCATIONS	E-1
APPENDIX F	ALL-EMPLOYEE MESSAGES	F-1
APPENDIX G	NEWS STORIES.....	G-1
APPENDIX H	FACILITY AND PROGRAM DESCRIPTION	H-1
APPENDIX I	PROJECT HANFORD LESSONS LEARNED	I-1
APPENDIX J	FRUIT FLY BIOLOGY AND HYPOTHETICAL SCENARIO.....	J-1

EXHIBITS

EXHIBIT A	OVERALL TIMELINE	ExA-1
EXHIBIT B	MAP OF 200 EAST AREA, SHOWING FACILITIES AND FLYING-INSECT TRAPS	ExB-1
EXHIBIT C	LOCATION MAPS OF FLYING-INSECT TRAPS.....	ExC-1
EXHIBIT D	MAP OF CITY OF RICHLAND LANDFILL.....	ExD-1

FIGURES

Figure 1. Hanford Site, Washington	1-2
Figure 2. 200 East Area, Hanford Site.....	1-3
Figure 3. Relationship of Facilities Near B Plant.....	1-4
Figure 4. Typical Diversion Pit	2-2
Figure 5. Drawing of the 241-ER-152 Diversion Pit.....	2-3
Figure 6. Compactor Refuse Truck.....	2-6
Figure 7. Diversion Pit 241-ER-152 with Tent	3-5
Figure 8. Event Summary – Emerging Fruit Flies Migrate to Dumpster.	3-7
Figure 9. B Plant Radiological Buffer Area.....	3-13
Figure 10. Flying-Insect Trap.....	3-15