

Tape #	VHS/SVHS	Date	Run Time	Area	Facility	SSC ID
12998		2012-09-26	00:45:33	200 East	AY-Farm	AY-102
12999		2012-09-19	00:38:55	200 East	AY-Farm	AY-102
13000		2012-09-18	00:20:08	200 East	AY-Farm	AY-102
13001		2012-09-24	04:24:27	200 East	AY-Farm	AY-102
13009		2012-09-04	00:28:53	200 East	AY-Farm	AY-102
13010		2012-09-26	01:18:15	200 East	AY-Farm	AY-102
13022		2012-09-07	00:55:32	200 East	AY-Farm	AY-102
13024		2012-09-07	01:14:28	200 East	AY-Farm	AY-102
13042		2012-09-17	00:17:43	200 East	AY-Farm	AY-102
13044		2012-09-13	00:15:19	200 East	AY-Farm	AY-102
13045		2012-09-20	00:10:17	200 East	AY-Farm	AY-102
13046		2012-09-24	00:11:35	200 East	AY-Farm	AY-102
13048		2012-09-07	00:43:39	200 East	AY-Farm	AY-102
13051		2012-09-07	01:06:18	200 East	AY-Farm	AY-102
13052		2012-09-05	00:48:45	200 East	AY-Farm	AY-102
13053		2012-09-10	00:18:07	200 East	AY-Farm	AY-102
13055		2012-09-10	00:18:01	200 East	AY-Farm	AY-102
13056		2012-09-06	01:12:14	200 East	AY-Farm	AY-102
13057		2012-09-05	01:36:28	200 East	AY-Farm	AY-102

Title
AY-102, Annulus Samples, Riser 91
AY-102, Leak Detection Pit - After Pumpout
AY-102, Leak Detection Pit
AY-102, Annulus Leak Detection Pit
AY-102, Annulus, Riser 90
AY-102, Annulus Sample, Riser 83
AY-102, Annulus, Riser 79
AY-102, Annulus, Riser 86
AY-102, Annulus, Riser 83
AY-102, Annulus, Riser 83
AY-102, Riser 83
AY-102, Riser 83
AY-102, Annulus, Riser 80
AY-102, Annulus, Riser 77
AY-102, Annulus, Riser 89
AY-102, Annulus, Riser 83
AY-102, Annulus, Riser 83
AY-102, Annulus, Riser 91
AY-102, Annulus, Riser 88

Customer	Comp -any	E R	Box #	Tape #	DVD#	DV D - M	DV D - W	Key Words & Remarks
Tank Farm Contractor	WRPS	Y		12998	0	Y	Y	
Tank Farm Contractor	WRPS	N		12999	0	Y	Y	
Tank Farm Contractor	WRPS	N		13000	0	Y	Y	
Tank Farm Contractor	WRPS	N		13001	0	Y	Y	
Tank Farm Contractor	WRPS	N		13009	0	Y	Y	
Tank Farm Contractor	WRPS	Y		13010	0	Y	Y	
Tank Farm Contractor	WRPS	N		13022	0	Y	Y	
Tank Farm Contractor	WRPS	N		13024	0	Y	Y	
Tank Farm Contractor	WRPS	N		13042	0	Y	Y	
Tank Farm Contractor	WRPS	N		13044	0	Y	Y	
Tank Farm Contractor	WRPS	N		13045	0	Y	Y	
Tank Farm Contractor	WRPS	N		13046	0	Y	Y	
Tank Farm Contractor	WRPS	N		13048	0	Y	Y	
Tank Farm Contractor	WRPS	N		13051	0	Y	Y	
Tank Farm Contractor	WRPS	N		13052	0	Y	Y	
Tank Farm Contractor	WRPS	N		13053	0	Y	Y	
Tank Farm Contractor	WRPS	N		13055	0	Y	Y	
Tank Farm Contractor	WRPS	N		13056	0	Y	Y	
Tank Farm Contractor	WRPS	N		13057	0	Y	Y	

Tape #	VHS/SVHS	Date	Run Time	Area	Facility	SSC ID
13247		2013-02-11	01:08:25	200 West	T-Farm	T-111
13314		2013-03-20	00:54:21	200 East	T-Farm	T-111
13894		2013-12-30	00:45:02	200 East	T-Farm	T-111
13895		2013-12-31	00:36:55	200 East	T-Farm	T-111

Title	
T-111, Riser 6 Video Inspection	
200 West, T-111, Primary Tank Inspection - Second Scan	
T-111, R-2 Primary Inspection, 12-30-13	
T-111, R-2 Primary Inspection, 12-31-13	

Customer	Comp -any	E R	Box #	Tape #	DVD#	DV D - M	DV D - W	Key Words & Remarks
Tank Farm Contractor	WRPS	N		13247	0	Y	Y	
Tank Farm Contractor	WRPS	Y		13314	0	Y	Y	
Tank Farm Contractor	WRPS	Y		13894	0	Y	Y	
Tank Farm Contractor	WRPS	Y		13895	0	Y	Y	