

Plutonium Finishing Plant Update

For the Week Ending June 9, 2019

Summary:

Completed demolition and load out of stairwell #1, part of the remaining lower-risk portion of the Main Processing Facility.

Key Accomplishments: (Week of June 2)

- Completed demolition of stairwell #1 on the Main Processing Facility
- Shipped 24 containers of demolition debris to ERDF

Safety Issues or Concerns:

- None

Radiological Issues or Concerns:

- None

Contamination Discovered Outside the Radiological Buffer Area (RBA):

- None

Bioassays Requested:

- None

Upcoming Work:

- Continue demolition on remaining lower-risk portion of the Main Processing Facility
- Continue shipments of debris to ERDF
- Continue resolution of corrective actions identified in the final Management Assessment report

Employee Interface:


- PFP management continues holding regular roundtables with employees.




Demolition of stairwell #1 of the Main Processing Facility was completed last week.

PFP HAZARD REDUCTION PROGRESS


MAR and Waste Reduction During Demo




Loaded Low Level Waste



Loaded Universal/Hazardous Waste



TRU Waste Dispositioning During Stabilization



MAR=Material at Risk (Plutonium)
234-52=Main Processing Facility

PRF=Plutonium Reclamation Facility
LLW RORO's=Low-Level Waste Roll-On Roll-Off Containers

TRU=Transuranic (Waste)
SLB2=Standard Large Box 2

SWB=Standard Waste Box